ORDINANCE NO. 3842

AN ORDINANCE TO DETERMINE THE ASSESSMENTS AGAINST THE PROPERTIES SPECIFICALLY BENEFITTED BY STREET IMPROVEMENTS, ST-74-23, GEARY STREET - 34TH TO 39TH, AMENDING ORDINANCE NOS. 3829 AND 3833 AND 3837 AND DECLARING AN EMERGENCY.

RECITALS:

- 1. The sewer assessment as referred to in this ordinance and previous resolutions and ordinances are the street improvement to serve ST-74-23, Geary Street 34th to 39th.
- 2. Preliminary resolutions and ordinances prescribing the manner and extent of the improvements are set forth in Resolution Nos.
- 3. The assessments set forth in the following ordinance are based upon the request and recommendation of the City Engineer in compliance with Ordinance No. 2864.

THE PEOPLE OF THE CITY OF ALBANY DO ORDAIN AS FOLLOWS:

Section 1: COST

The total cost of the Street improve to serve ST-74-23, Geary Street - 34th to 39th is as follows:

Project	SCF	Cost	15% E.L.A.	<u>Total</u>
ST-74-23, Geary Street	14,649.58 4	5,008.30	8,750.98	66,409.12

Proposed by Carl Fair

Section 2:

PROPERTY AND ASSESSMENT DATA - ATTACHED SHEETS

Section 3:

The City Recorder is hereby directed to enter a statement of the assessments as above provided in the docket of the City Liens and give notice thereof as provided by law.

Section 4:

Inasmuch as this ordinance is necessary for the immediate preservation of the peace, health and safety of the City of Albany, Oregon, an emergency is hereby declared to exist and this ordinance shall be in full force and effect immediately upon passage by the Council and approval by the Mayor.

Passed by the Council: April 12, 1975
Approved by the Mayor: April 12, 1975
Effective Date: April 12, 1975

ATTEST:

City Recorder

Interdepartmental Memorandum Engineering Department

SUB	JECT:	Final Assessment: ST 74-23 Geary (Project Name		(Revised)		
TO:		City Manager	alla italia	,,		
FRO		Carl Fair, Eng. Tech. III				
FKU	I*I .	Call Fall, Eng. Tech. III				
DAT	E:	February 26, 1975		•		
					•	
A.	1. S 2. S	CCT COSTS DATA CCF Oversizing Cost CCF Intersection Cost CCF Corner Lot Credit \$6,060.06	· ·			
	3. 3	\$18.90 x 100.00 1,890.00 (Cost) (Feet)				
	5. F	Total SCF Construction Cost Property Owner Construction Cost TOTAL CONSTRUCTION COST		\$ 7,950.06 46,330.20	\$54,280.26	
В.	ASSES	SSMENT COSTS				
þ	1. S	SCF Assessment a. SCF Construction Cost \$7,950.06 b. ELA - 15% 1,192.51 c. Total SCF Assessment			9,142.57	
	2. F	roperty Owner Assessment		46 770 20		=
	_	. Property Owner Construction Cost . ELA - 15%		46,330.20 6,949.53		
		Collection for SCF		0,345.33		
		\$3.20 × 2734.68		8,750.98	:	
	٠ ,	(Cost) (Fr.Ft.) Narrant Interest		740.65		
		c. Other: Assessable D/Ws		3,381.48		
		Total Assessable Cost to Property (Owner		66,152.84	
	Cost	per front foot = \$62,771.36 / 2705		= \$23.199846	/fr.ft.	-
		(cost) (fr	r.ft.)			

METHOD OF ASSESSMENT

PROPERTY AND ASSESSMENT DATA

Please refer to attached sheets.

Respectfully submitted,

Carl Fair, Eng. Tech. III

gm

PROPERTY ASSESSMENT DATA

Pro	ject:) 74-23 Geary St	reet - 34th Avenue to 39th	1)		· <u>································</u>	·	February 26	<u>, 1975</u>
No.	Owner & Address	Description/Tax Lot No.	Total Fr. Ft.	C.L.C.	Assess Fr.Ft.		Area D/W Sq. Ft.	D/W Asse ss- ment	Total Assess- ment
1	Dunford, Arlow A. 3400 South Geary Albany, OR	11 3W 17CC 300 118535	78.0	50.0	28.0	\$ 649.60	90.0	\$121.50	\$ 771.10
2	Marrs, Richard E. 3408 South Geary Albany, OR	11 3W 17CC 400 118543	100.0		100.0	2,319.98	105.0	141.75	2,461.73
3	Wiley, Archie 3416 South Geary Albany, OR	11 3W 17CC 500 118550	100.0		100.0	2,319.98	164.15	221.60	2,541.
4	Woods, Raymond M. 3504 South Geary Albany, OR	11 3W 17CC 600 118568	100.0		100.0	2,319.98	230.0	310.50	2,630.48
5	Emmett, Leland W. 3512 South Geary Albany, OR	11 3W 17CC 700 118576	100.0		100.0	2,319.98	125.0	168.75	2,488.73
6	Hay, Robert F. 3520 South Geary Albany, OR	11 3W 17CC 800 118584	100.0		100.0	2,319.98			2,319.98
7	Mueller, Arthur C. 3608 South Geary Albany, OR	11 3W 17CC 900 118592	100.0		100.0	2,319.98	120.0	162.00	2,481.98
8	Farmer, Rex D. 3616 South Geary Albany, OR	11 3W 17CC 1000 118600	100.0		100.0	2,319.98	108.75	146.81) 2,466.79
9	Hanson, Harry M. 3624 South Geary Albany, OR	11 3W 17CC 1100 118618	100.0	·	100.0	2,319.98	139.15	187.85	2,507.83
10	Bohard, Kenneth E. Bray, Bruce D., Agt. 3702 South Geary	11 3W 17CC 1200 118626	100.0		100.0	2 710 00			2,319.98
	Albany, OR		100.0		100.0	2,319.98			4,313.30

PROPERTY ASSESSMENT DATA

Pro	ject: 🏋 74-23 Geary Str	cet - 34th Avenue to 39th	1					February .) 19.
No.	Owner & Address	Description/Tax Lot No.	Total Fr. Pt.	C.L.C.	Assess Fr.Ft.		Area D/W Sq. Ft.	D/W Assess- ment	Total Assess- ment
11	Konopa, Thomas J. 3710 South Geary Albany, OR	11 3W 17CC 1300 118634	.100.0		100.0	\$2,319.98	103.0	\$139.05	\$2,459.03
12	Ritchie, Donald E. 3718 South Geary Albany, OR	11 3W 17CC 1400 118642	100.0		100.0	2,319.98		•	2,319.98
13	Wilson, Ruth M. 3405 South Geary Albany, OR	11 3W 17CA 1000 116349	91.18		91.18	2,115.36			2,115.36
14	Mark, Wing 3413 South Geary Albany, OR	11 3W 17CA 1100 116356	106.0		106.0	2,459.18	203.05	274.12	2,733.30
15	Citizen Valley Bank 3421 South Geary Albany, OR	11 3W 17CA 1200 116364	106.0		106.0	2,459.18			2,459.18
16	Kastner, Ed F. 1310 South Powell Albany, OR	11 3W 17CA 1300 116372	106.0		106.0	2,459.18			2,459.18
17	Settlemeyer, T. H. Weaver, Gary L., Agt. 3515 South Geary Albany, OR	11 3W 17CA 1400 116380	126.0		126.0	2,923.18	A		2,923.18
18	Meade, Donald E. 3603 South Geary Albany, OR	11 3W 17CD 102 119574	75.0		75.0	1,739.99	155.0	209.25	1,949.24
19	Perlenfein, Russell C. 3620 South Columbus Albany, OR	11 3W 17CD 200 119582	82.75		82.75	1,919.80			1,919.80
20	Hardesty, A. E. 3617 South Geary Albany, OR	11 3W 17CD 300 119608	98.0		98.0	2,273.58		. •	2,273.58

3

PROPERTY ASSESSMENT DATA

Pro	oject:) 74-23 Geary Str	reet - 34th Avenue to 39th	<u>h</u>)				,	February 2	<u>v, 1</u> 5
No.	Owner & Address	Description/Tax Lot No.	Total Fr. Ft.	C.L.C.	Assess Fr.Ft.		Area D/W Sq. Ft.	D/W Assess- ment	
21	Wines, Marvin P. et al 2221 Santiam Highway Albany, OR	11 3W 17CD 407 119699	77.50		77.50	\$1,798.00	129.15	\$174.35	\$1,972.35
22	H	11 3W 17CD 411 353538	100.75		100.75	2,337.38	139.0	187.65	2,525.03
23	11	11 3W 17CD 405 119673	77.50		77.50	1,798.00	133.75	180.56	1,978.56
24		11 3W 17CD 521 336491	101.0		101.0	2,343.18	134.15	181.10	2,524.
25	**	11 3W 17CD 513 332847	59.20	•	59.20	1,373.43			1,373.43
26	Jones, Dennis Formerly Bylund, Marcia 3806 South Geary Albany, OR	11 3W 20 TL 400 a 127411	150.0		150.0	3,479.98	105.65	142.63	3,622.61
27	Chapman, George 3812 South Geary Albany, OR	11 3W 20 TL 501 127437	64.0		64.0	1,484.80	175.0	236.25	1,721.05
. 28	Wines, Marvin P. et al 2221 Santiam Highway Albany, OR	11 3W 17CD 514 332854	73.40		73.4	1,702.88	\ -	-	1,702.88
29	Stockton, Shirley C. 1807 East 39th Albany, OR	113W 17CD 506 332763	73.40	50.0	23.4	542.88			542.08
30	Wines, Marvin P. et al 2221 Santiam Highway Albany, OR	11 3W 17CD 538 369104	60.0		60.0	1,392.00	145.0	195.75	1,587.75
	TOTALS	The Mark Mark Control of the Section	2,805.68	100.0	2,705.68	\$62,771.3	36 2504.8	\$3,381.48	\$66,152.84

337